Technical Bulletin
Concrete Roof Tile Surface Marks

ISSUED: OCTOBER 15, 2026

Occurrence During Shipping and Handling


Scuff marks may appear on concrete roof tiles during shipping and handling. These marks are typically caused by **minor disturbances to the factory-applied sealer.**

Temporary Nature of Scuff Marks

These scuff marks are **temporary and will fade** as the sealer weathers over time.

Impact on Tile Appearance and Integrity

The presence of scuff marks **does not affect the color of the tiles or their structural integrity.**



For more information, contact your local Eagle Account Representative by visiting eagleroofing.com.